PROCESS CHART

Receive Enquiry

Capability Check → Reject → Analysis & Improvement

Capability Check → Send Offer

Send Offer → Acceptance by Customer

Acceptance by Customer → Receipt of Drawing & P.O. Raw Meterial Forecast

Receipt of Drawing & P.O. Raw Meterial Forecast → Loading Memo Drawings & Parts List

Receipt of Drawing & P.O. Raw Meterial Forecast → Sub Contact Requirment

Sub Contact Requirment → Raise Indent for R/M

Raise Indent for R/M

Procurement of R/M & B/O Items Raise P.O. → Production Groups Raise Requirement for R/M/O Items Machining Shearing Sub Contracion

Procurement of R/M & B/O Items Raise P.O. → Receipts of Items

Receipts of Items → QC Inspection

QC Inspection → Issue of R/M & B/O Items

Manufacturing Process

QC Inspection → Reject and Backload

QC Inspection → QC Inspection Ip- 2 & Ip- 3

QC Inspection Ip- 2 & Ip- 3 → Layout Inspection In Process Inspection End Product Inspection

QC Inspection Ip- 2 & Ip- 3 → End Product for Painting/ Packing/ Despatch